



Photo#1: Overview of Location to South



Photo#2: Location is Open to Traffic. Land Owner put Logs at entry and No Trespassing Sign in attempt to stop incursions.





Photo#3: Evidence of ATV Traffic on Location.



Photo#4: Vegetation is emerging.





Photo#5: Wattles are being overwhelmed by excessive Runoff from Location; also more evidence of ATV damage to BMPs.



Photo#6: Stormwater undercutting Wattles at South end of Location.





Photo#7: Revegetating areas and drainage swales need stabilizing BMPs installed until vegetation is established.



Photo#8: Erosion, channeling, flowing from center of Location to West.