

On September 2, 2016 COGCC Environmental Field Inspection of DIVERSIFIED ENERGY LLC
(Diversified) Bingham Location ID: 313094.



Location sign.



View walking up lease road.



Looking west across Location.



Bingham 1-14 well.



Oil staining on soil around well head.



Stainless steel chemical container.



5-gal container at well head.



Vegetation (weeds).



Tank battery, berm vegetation (weeds)..



Black poly riser south side of tank battery.



Land treatment area.



Land treatment area.



Land treatment area.



Pit Facility 285519.



Pit Facility 285519.



Surface flow to Pit Facility 285519.



Surface flow into Pit Facility 285519. Note black poly pipe in center of photo.



Black poly pipe protruding from pit wall.



Area of surface disturbance and mended fence along (black poly pipe).



Mended fence.



Raised disturbed area from Pit Facility to tank battery.



Riser on south side of the tank battery.