

Robidoux 13-7

Inspection# 673403652

Well free flowing from tubing valve on left at time of arrival on location.



Spill pathway looking north towards wellhead.



End of spill pathway.



Tank label (NFPA diamonds) incomplete.



Overflow path.



Spill contained in berm.



Spill contained in berm.



Spill contained in berm.



Spill contained in berm.



Material added to spill, in berm.



Surface disturbance, in berm.

