

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2016

Submitted Date:

09/19/2016

Document Number:

685301438**FIELD INSPECTION FORM**Loc ID 306943 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------------|---------------------------------------|
| Notor, Lori | 505-326-9822 | Lori.R.Notor@conocophillips.com | SW Inspection Reports |
| Roberts, Kelly | 505-326-9775 | Kelly.Roberts@conocophillips.com | SW Inspection Reports |
| Busse, Dollie | 505-324-6104 | dollie.l.busse@conocophillips.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 281264 | WELL | PR | 02/13/2006 | GW | 067-09086 | LEVEY 100S | PR |

General Comment:

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------|----------------------|--|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | |
| | Date: | <input type="text"/> | |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Post and Wire | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Safety Rails | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Post and Hog Wire | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric Service | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---------------------|--|-------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric Motor | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry Equipment | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|----------------|----------|----------|----------|--------|--|
| Contents | # | Capacity | Type | Tanak ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | Open Top | | , | |
| Comment: | Steel Mesh Top | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 120 BBLS | |
| Other (Type) | | |

Berms

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tanak ID | SE GPS | |

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|---|-------|
| PRODUCED WATER | 2 | 500 BBLs | HEATED STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

| Inspected Facilities | | | |
|----------------------|------------|-----------------------|------------|
| Facility ID: 281264 | Type: WELL | API Number: 067-09086 | Status: PR |
| Insp. Status: PR | | | |
| Producing Well | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | Culverts | | | | |
| Ditches | Pass | | | | | |
| Berms | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 685301438 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3957093 |