

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2016

Submitted Date:

09/20/2016

Document Number:

666802583

FIELD INSPECTION FORM

Loc ID 334821 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211052	WELL	PR	06/15/2002	GW	045-06810	COUEY T8-42	PR
261758	WELL	PR	08/07/2002	GW	045-07975	COUEY 8-10B	PR
261759	WELL	PR	05/16/2002	GW	045-07976	COUEY 8-10A	PR

General Comment:

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities			
Facility ID: <u>211052</u>	Type: <u>WELL</u>	API Number: <u>045-06810</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: <u>261758</u>	Type: <u>WELL</u>	API Number: <u>045-07975</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: <u>261759</u>	Type: <u>WELL</u>	API Number: <u>045-07976</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Plunger lift		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
Ditches	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802583	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3957429