

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2016

Submitted Date:

09/21/2016

Document Number:

674103666

### FIELD INSPECTION FORM

Loc ID 319917 Inspector Name: Rickard, Jeff On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 27635  
 Name of Operator: ENERGY SEARCH COMPANY  
 Address: PO BOX 1896  
 City: EDWARDS State: CO Zip: 81632

**Findings:**

- 1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Marisco, Joe		joemarisco@yahoo.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Axelson, John		john.axelson@state.co.us	
Roebuck, Don		don_roebuck@msn.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201883	WELL	PR	02/19/2015	OW	001-07287	GINTHER 1	PA

**General Comment:**

**Inspected Facilities**Facility ID: 201883 Type: WELL API Number: 001-07287 Status: PR Insp. Status: PA**Complaint**

Comment: OGCC inspector was on location on 9/21/16 to investigate for Complaint# 200440346. OGCC inspector found no active leaks. Well documentation has a Form 42 for start of plugging operations dated 09/08/16. Well appears to have been plugged at the time of this inspection. Wellhead parts and casing are piled on the SE side of the pump jack. Any evidence of the spill provided in the photo from complainant has been removed as evidenced by scratch marks from a front loader (see photos). The source of the release is unable to be determined at his time. Photos of the location are attached to this report.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103667	Location overview on 9/21/16	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958498</a>
674103668	Wellhead parts and casing piled on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958499</a>
674103669	Location from the south looking north.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958500</a>
674103670	Location from the north looking south.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958501</a>