

Location

Overall Good:

Signs/Marker:

	Type DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	719-691-9443		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 218009 Type: WELL API Number: 073-05055 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Murfin Rig 25 Pusher/Rig Manager: Ray
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
 Multi-Well: NO Disposal Location: onsite

Comment: Skidded rig 75' south of Schulte 1-13R. Pump is currently over Schulte 1-13R-not cut, capped or covered yet. Extended drill pit south a strip on the west side. Berms and a compacted new topsoil stockpile added. Surface roughening around new construction. Drilled to 432' (KB 13') pipe to 425' (9 5/8", 36 weight)-(Wyoming Casing); welded (SAE Welding). Took down fence on south side of location to skid rig.

Corrective Action: _____ Date: _____

Cement

Cement Contractor

Contractor Name: Consolidated Contractor Phone: 785-672-8822

Surface Casing

Cement Volume (sx): 325 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Class A cement. Three BBLs circulated to pit. Cementing not observed by inspector.

Corrective Action: _____ Date: _____

Facility ID: 447809 Type: WELL API Number: 073-06715 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Tracking Pad	Pass	Spill Response	Pass	
Waddles	Pass					
Compaction	Pass					
Slope Roughening	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673714010	Grynbeg Schulte 1-13	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3958852