

Bayswater Exploration & Production
(Operator # 10261) Cockroft Farms
Land Application Site (COGCC Facility
ID 441086)
COGCC Site Inspection – 9/21/2016



Photo 1 taken in Section A, looking west (40.395985 / -104.471801)

Area where fluids were removed, current fluid appears to be stormwater and/or irrigation runoff



**Photo 2 taken in northeast corner Section A looking northeast
(40.395267 / -104.470958)**

Stockpiled drill cuttings in Section A.



Photo 3 on east end of Section A looking north (40.395037 / - 104.470281)

Stockpiled drill cuttings



Photo 4: Cuttings intermixed with straw bales and manure piles in distance, looking west (40.395496 / -104.471381)



**Photo 5 looking north at cuttings adjacent the Cockroft 19V location
(wellhead is on the right side of photo) (40.388613 / -104.470883)**



**Photo 5 looking south at cuttings adjacent the Cockroft 19V location
(wellhead is on the left distant side of photo) (40.389658 / -104.470427)**