



photo 1: Facing southeast along the access road toward the location. There is erosion occurring across the main road and there is no culvert present to divert stormwater.



photo 2: There is erosion occurring across the main road and there is no culvert present to divert stormwater. Red arrow points to 3 ft. shovel.



photo 3: Facing northwest toward the location off the main road.



photo 4: Facing west toward the cut where there is signs of erosion.