



**photo 1:** There is an erosion channel along the main road near the location.



**photo 2:** Facing back toward the east at the location. There are signs of stormwater flowing toward the main road causing erosion.





**photo 3:** There was a dripping water leak noticed at the well head.



**photo 4:** Facing toward the pit at the southwest side of the location.