



**photo 1:** Facing west along the main access road. There are signs of erosion occurring on the main road.



**photo 2:** The culvert along the access road is filling in with sediment.





**photo 3:** The culvert along the main road has filled in with sediment.



**photo 4:** There is erosion occurring along the access road. Red arrow points to 3 ft. shovel.





**photo 5:** The culvert along the main road is filled in with sediment.



**photo 6:** Facing southwest along the fill slope of the location.





**photo 7:** Facing west toward the location.



**photo 8:** Facing toward the northwest side of the location. There are signs of erosion along the cut slope.