



photo 1: Facing west along the main access road. Sediment has filled in the culverts. Stormwater flowed across the road which washed away gravel and deposited sediment on the road.



photo 2: Facing west along the main access road. Sediment has filled in the culverts. Stormwater flowed across the road which washed away gravel and deposited sediment on the road.



photo 3: The culvert along the main road has filled in with sediment.



photo 4: Facing west along the main road near the location. There are signs of erosion occurring on the road.



photo 5: Facing toward the northwest cut slope. There are signs of erosion in this area.



photo 6: The vegetation along the west side of the location is predominately weed growth.