



photo 1: Facing west along the main access road. The culverts are filled with sediment and stormwater washed away gravel and deposited sediment on the road.



photo 2: Facing west along the main access road. The culverts are filled with sediment and stormwater washed away gravel and deposited sediment on the road.



photo 3: Facing west toward the location. There are signs of erosion at this area.



photo 4: Facing northwest at the location.