



Photo#1: Over view of Location from Entry Road .

September 6, 2016

Inspection Photos: Chevron PR API#045-17284



Photo#2: C List Weeds Established in Interim areas.

September 6, 2016

Inspection Photos: Chevron PR API#045-17284

Photos #3 & 4: Rill erosion and Sediment Run On to Location.



September 6, 2016

Inspection Photos: Chevron PR API#045-17284



Photo#4: Erosion Channel developing at NE Corner of Cut Slope.

September 6, 2016

Inspection Photos: Chevron PR API#045-17284



Photo#5: API# 045-17284 is now assigned to Location with 23 other Wells.

September 6, 2016

Inspection Photos: Chevron PR API#045-17284