

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/06/2016

Submitted Date:

09/22/2016

Document Number:

680101141

FIELD INSPECTION FORM

Loc ID 336050	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED											
2A Doc Num: _____			Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested											
Operator Information: OGCC Operator Number: 16700 Name of Operator: CHEVRON USA INC Address: 6301 DEAUVILLE BLVD City: MIDLAND State: TX Zip: 79706														
Contact Information:														
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Grubbs, Richard</td> <td>970-257-6021</td> <td>rtgrubbs@chevron.com</td> <td></td> </tr> <tr> <td>Longworth, Mike</td> <td></td> <td>mike.longworth@state.co.us</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	Grubbs, Richard	970-257-6021	rtgrubbs@chevron.com		Longworth, Mike		mike.longworth@state.co.us
Contact Name	Phone	Email	Comment											
Grubbs, Richard	970-257-6021	rtgrubbs@chevron.com												
Longworth, Mike		mike.longworth@state.co.us												

Contact Name	Phone	Email	Comment
Grubbs, Richard	970-257-6021	rtgrubbs@chevron.com	
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295965	WELL	PR	08/02/2012	GW	045-15865	SKR 698-09-AV-04	RI
298601	WELL	PR	07/19/2012	GW	045-17281	SKR 698-09-AV-03	RI
298602	WELL	PR	07/01/2013	GW	045-17282	SKR 698-09-AV-22	RI
298603	WELL	PR	09/01/2012	GW	045-17283	SKR 698-09-AV-21	RI
298604	WELL	PR	08/01/2013	GW	045-17284	SKR 698-09-AV-20	RI
298605	WELL	PR	08/31/2012	GW	045-17285	SKR 698-09-AV-19	RI
298606	WELL	PR	07/01/2013	GW	045-17286	SKR 698-09-AV-18	RI
298607	WELL	PR	07/01/2013	GW	045-17287	SKR 698-09-AV-16	RI
298608	WELL	PR	08/25/2012	GW	045-17288	SKR 698-09-AV-15	RI
298610	WELL	PR	08/08/2012	GW	045-17289	SKR 698-09-AV-14	RI
298611	WELL	PR	08/23/2012	GW	045-17290	SKR 698-09-AV-13	RI
298612	WELL	PR	12/13/2011	GW	045-17291	SKR 698-09-AV-12	RI
298613	WELL	PR	12/10/2011	GW	045-17292	SKR 698-09-AV-11	RI
298614	WELL	PR	12/20/2011	GW	045-17293	SKR 698-09-AV-10	RI
298615	WELL	PR	12/24/2011	GW	045-17294	SKR 698-09-AV-09	RI
298616	WELL	PR	07/01/2013	GW	045-17295	SKR 698-09-AV-08	RI
298617	WELL	PR	12/07/2011	GW	045-17296	SKR 698-09-AV-07	RI
298618	WELL	PR	07/17/2012	GW	045-17297	SKR 698-09-AV-01	RI
298619	WELL	PR	07/31/2012	GW	045-17298	SKR 698-09-AV-02	RI
298620	WELL	PR	07/22/2012	GW	045-17299	SKR 698-09-AV-05	RI
298621	WELL	PR	08/29/2012	GW	045-17300	SKR 698-09-AV-17	RI
298622	WELL	PR	04/14/2012	GW	045-17301	SKR 698-09-AV-06	RI
412116	WELL	PR	08/01/2013	GW	045-18438	SKR 698-09-AV-24	RI

412117	WELL	PR	07/14/2012	GW	045-18439	SKR 698-09-AV-23	RI
--------	------	----	------------	----	-----------	------------------	----

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Inspection was prompted by PR Well API#045-17284 being identified as Interim Reclamation Priority. The Well has No Inspections on Record; it was assigned to Location #3244501. It is on same site as Location #336050 with 23 other PR Wells, which have had Inspections. Operator, Chevron has all 24 Wells assigned to their 698-09-AV Pad. After Notification COGCC staff has reassigned Well to the Loc#336050 with the 23 other Wells.

Inspected Facilities				
Facility ID: <u>295965</u>	Type: <u>WELL</u>	API Number: <u>045-15865</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298601</u>	Type: <u>WELL</u>	API Number: <u>045-17281</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298602</u>	Type: <u>WELL</u>	API Number: <u>045-17282</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298603</u>	Type: <u>WELL</u>	API Number: <u>045-17283</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298604</u>	Type: <u>WELL</u>	API Number: <u>045-17284</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298605</u>	Type: <u>WELL</u>	API Number: <u>045-17285</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298606</u>	Type: <u>WELL</u>	API Number: <u>045-17286</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298607</u>	Type: <u>WELL</u>	API Number: <u>045-17287</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298608</u>	Type: <u>WELL</u>	API Number: <u>045-17288</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298610</u>	Type: <u>WELL</u>	API Number: <u>045-17289</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298611</u>	Type: <u>WELL</u>	API Number: <u>045-17290</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298612</u>	Type: <u>WELL</u>	API Number: <u>045-17291</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298613</u>	Type: <u>WELL</u>	API Number: <u>045-17292</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298614</u>	Type: <u>WELL</u>	API Number: <u>045-17293</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298615</u>	Type: <u>WELL</u>	API Number: <u>045-17294</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298616</u>	Type: <u>WELL</u>	API Number: <u>045-17295</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298617</u>	Type: <u>WELL</u>	API Number: <u>045-17296</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298618</u>	Type: <u>WELL</u>	API Number: <u>045-17297</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>298619</u>	Type: <u>WELL</u>	API Number: <u>045-17298</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Inspector Name: Colby, Lou

Facility ID:	298620	Type:	WELL	API Number:	045-17299	Status:	PR	Insp. Status:	RI
Facility ID:	298621	Type:	WELL	API Number:	045-17300	Status:	PR	Insp. Status:	RI
Facility ID:	298622	Type:	WELL	API Number:	045-17301	Status:	PR	Insp. Status:	RI
Facility ID:	412116	Type:	WELL	API Number:	045-18438	Status:	PR	Insp. Status:	RI
Facility ID:	412117	Type:	WELL	API Number:	045-18439	Status:	PR	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? InProduction areas have been stabilized? Pass

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured Pass80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment Patchy areas of Interim have heavy Population of C List Weeds. Operator advised to control these Weeds, helping Perennial Vegetation to establish; reseeding if needed.

Corrective Action

Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____Contoured _____Culverts removed _____Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Inspector Name: Colby, Lou

Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass					
Comment: <input type="text" value="Rill Erosion in areas of Cut Slope is causing sediment Run On to Location."/>						
Corrective Action: <input type="text" value="Install appropriate BMPs to Stabilize eroding areas of Cut Slope"/> Date: <input type="text" value="10/31/2016"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101142	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960236