

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2016

Submitted Date:

09/22/2016

Document Number:

666802596**FIELD INSPECTION FORM**

Loc ID 324383 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429482	WELL	PR	07/05/2013	GW	045-21608	MCU 26-4A (I27W)	PR

General Comment:[Inspection is for Bradenhead test](#)

Inspected FacilitiesFacility ID: 429482 Type: WELL API Number: 045-21608 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

BradenHeadComment: Form 17 filled out by operator and signed by COGCC staff, Start 150psi, steady gassing thru test, No fluid to surface

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802596	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3960277