

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2016

Submitted Date:

09/26/2016

Document Number:

679500151

## FIELD INSPECTION FORM

 Loc ID 320287 Inspector Name: AXELSON, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 8840Name of Operator: BLUE CHIP OIL INCAddress: 155 E BOARDWALK DR STE 400City: FORT COLLINS State: CO Zip: 80525**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
John Mahoney		jmahoney2644@comcast.net	
,	970-493-6456	bluechipoil@msn.com	all inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203360	WELL	PR	10/06/2015	OW	001-08869	NORTHSTAR 24-2	EI

**General Comment:**

Environmental Inspection performed in response to Complaint #200440165. Operator discovered a problem during flowline testing and found historic impacts related to a concrete water vault that had been taken out of service some time in the past and replaced with an above ground fiberglass tank. Operator removed vault and began excavating impacted soil. At time of inspection, operator was continuing to excavate impacted soil at the tank battery. Approximately 100 cubic yards of waste had been removed from the location and disposed under manifests at Front Range Landfill in Erie, CO in accordance with COGCC Rule 907.e. An additional 40 cu yds were stockpiled pending off site disposal. Temporary stockpile was covered with plastic to prevent stormwater contamination in case of rain. Excavation was approximately 15' x 15' x 12' deep at time of inspection. Groundwater had not been contacted and no free liquids were observed in excavation. Nearby gas line was located over 20-feet west of the west wall of the excavation. Gas line operator had been notified and provided locates prior to excavation. Excavation was secured with fencing and signs at the end of the day.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Berms on south side of tank temporarily removed during remedial activity.			
Corrective Action:	Restore secondary containment in accordance with Rule 906.d.(1) after remediation is completed and prior to resumption of production.			Date: <u>10/31/2016</u>

**Venting:**

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 203360 Type: WELL API Number: 001-08869 Status: PR Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: An historical release was discovered related to a concrete water vault. Refer to Spill/Release Point ID #447758.

Corrective Action: Submit a supplemental eForm 19 in accordance with Rule 906. Submit a Form 27 to Date: 10/31/2016

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Keep stockpiled waste covered pending off site disposal, prevent stormwater contamination and control erosion during remedial activity.

Date: 10/31/2016

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
At the conclusion of remediation submit a closure report under an approved Form 27 with all soil disposal documentation, sample location diagram including depth the samples were collected, summary table comparing results to Table 910-1 standards and a copy of the lab reports. Include photo documentation and a narrative of the work completed.	axelsonj	09/26/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679500152	Excavation Fenced	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962012">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962012</a>
679500153	Excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962013</a>
679500154	Temporary stockpile pending disposal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962014">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962014</a>
679500155	Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962015</a>