

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2016

Submitted Date:

09/27/2016

Document Number:

671000454**FIELD INSPECTION FORM**Loc ID 335680 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                      | Comment                      |
|------------------|-------|----------------------------|------------------------------|
| Middleton, Brett |       | Brett.Middleton@encana.com | Environmental Specialist     |
| Fischer, Alex    |       | alex.fischer@state.co.us   | Environmental Supervisor, NW |
| Kasten, Matt     |       | Matthew.Kasten@encana.com  | Environmental                |
| Rider, Lindsey   |       | Lindsey.Rider@encana.com   | Manager, Field Environmental |
| Lujan, Carlos    |       | carlos.lujan@state.co.us   | EPS, NW Region               |
| Spencer, Stan    |       | stan.spencer@state.co.us   | EPS, NW Region               |

**General Comment:**

Environmental Inspection conducted on 09/20/2016. ON Site with Brett Middleton from Encana. Sunny and cool. Pit was backfilled with material that was not in compliance yet. Approximately 10 boreholes were recently drilled on the pit location (footprint). According to Encana only one sample presented concentrations above Table 910-1 and still requires some in-situ remediation. Pit Facility ID #335680 will remain ACTIVE until remediation is completed. Same for REM #9307. There is one Encana active well onsite (API 045 15497) and an injection well operated by Hunter Ridge (API 045 15495).

No weeds, staining or junk was observed onsite.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Notify COGCC via e-form 04 Notice of Completion, when remediation is completed. Submit analytical results.</a> | lujanc | 09/25/2016 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 671000456    | Encana Poduction Well       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962368">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962368</a> |
| 671000457    | Hunter Ridge Injection Well | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962369">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962369</a> |
| 671000458    | Stickups Boring Locations   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962370</a> |