

Stormwater Inspection



Photo 1. Photo taken from the lease road, facing East. Straw bales installed to control sedimentation from leaving lease road. Stormwater could possibly travel around straw bales because location lacks diversion features.

Stormwater Inspection



Photo 2. Photo taken from the lease road, facing North. Straw bales installed to control sedimentation from leaving lease road. Stormwater could possibly travel around straw bales because location lacks diversion features.