

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2016

Submitted Date:

09/27/2016

Document Number:

682401284

FIELD INSPECTION FORM

Loc ID 319062 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------|---------------------------------|
| Pape, Terry | 970-768-5700 | tpape@hrmres.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 242813 | WELL | PR | 03/26/1982 | GW | 123-10604 | MANDY 43-28 | RI |

General Comment:

[This is a follow up stormwater inspection to the previous corrective action inspection Document #682400638 issued on 4/19/2016.](#)

Inspected Facilities

Facility ID: 242813 Type: WELL API Number: 123-10604 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-----------------------|
| Waddles | Pass | | | | | Need to maintain BMPs |

Comment: [Straw bales installed to control sedimentation from leaving lease road. Stormwater could possibly travel around straw bales because location lacks diversion features.](#)
[Refer to attached photos in Document #682401286.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 682401284 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3963028 |
| 682401286 | Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3963022 |