

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/28/2016

Document Number:

674602845

**FIELD INSPECTION FORM**

Loc ID 303314 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69760  
Name of Operator: PETRON DEVELOPMENT COMPANY  
Address: 1899 W LITTLETON BLVD  
City: LITTLETON State: CO Zip: 80120

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Jimmy	(303) 794-5300	jim@petron.net	
Sherman, Susan		susan.sherman@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252889	WELL	PR	06/08/1982	GW	125-06765	BROWN 13-1	EG

**General Comment:**

COGCC engineering integrity and field inspection staff met with Petron Development representatives on location and conducted an engineering integrity field inspection. While on location the group discussed details of production operations and integrity program specifics for the gas and produced water flowlines associated with this well. Photo's have been uploaded and can be accessed via link(s) at the end of this report. This is an engineering integrity/ FLIR inspection (only).

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Flow Line		
Comment:	2" Carbon steel well site flowline (above ground) to meter run; 2" Poly (HDPE/ SDR 7) produced water dump line (directly from wellhead/ no separator) to pit; No integrity issues observed during this field inspection.	
Corrective Action:		Date: _____

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date: _____

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: _____

**Inspected Facilities**

Facility ID: 252889 Type: WELL API Number: 125-06765 Status: PR Insp. Status: EG

