

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/26/2016

Document Number:

685301478

FIELD INSPECTION FORM

Loc ID 325409 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214726 | WELL | PR | 05/15/1980 | GW | 067-06330 | SHARP 1E | SI |

General Comment:

Inspection report contains corrective action and comment. See Facilities Section of report for additional details. See link at end of report for path to downloadable pictures.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------|--|-------|
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Panel - Telemetry Equipment | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|---------------------|--|-------|
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry Equipment | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|----------|----------|--------|
| PRODUCED WATER | 1 | OTHER | Open Top | | , |
| Comment: | Fiberglass tank with chicken wire wildlife screen across top. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 22 BBLS | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|------------------|
| Earth | Inadequate | Walls Insufficient | Base Insufficient | Inadequate |
| Comment: | Berms are worn down to nonexistent. Animal burrows noted around tank and berms. | | | |
| Corrective Action: | Install or repair berms or other secondary containment device to comply with Rule 605.a. (4). | | | Date: 10/31/2016 |

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95 BBLS | |
| Other (Type) | | |

| Berms | | | | |
|---|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: Several animal burrows noted in containment berms. | | | | |
| Corrective Action: | | | | Date: |

| Venting: | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Flaring: | | | | |
|--------------------|--|--|--|-------|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 214726 Type: WELL API Number: 067-06330 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Gravel | Pass | | | |
| Berms | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 685301481 | Tank view 1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3964153 |
| 685301482 | Tank view 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3964154 |
| 685301483 | Tank view 3 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3964155 |