

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/02/2016

Submitted Date:

09/27/2016

Document Number:

677900186**FIELD INSPECTION FORM**

Loc ID 312772	Inspector Name: FISCHER, ALEX	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:

OGCC Operator Number: 10528

Name of Operator: ARCH OIL & GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75248

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Browning, Jeff	940-391-7210	jbrowning@matthewssouthwest.com	All Inspections
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222312	WELL	PR	12/01/2014	OW	081-05288	A.P. URIE 2	EI

General Comment:

On September 2, 2016 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of ARCH OIL AND GAS (Arch) Urie # 2 Location ID: 312772. The INSP included Tank Battery, the well (API 05-081-05288), tank battery, and Location. Weather was sunny to partially cloudy and temperature app mid 60s degree F and wind from the south. The well was not producing at time of inspection. For the most recent Field and Environmental Field inspection report of this facility, please refer to document # 673403544. At the time of the inspection, corrective actions (CAs) provided in that inspection had not been addressed. The overall inspection status shall remain the same as that document until all CAs have been completed. The following is a summary:

Well head:

Chemical containers not within secondary containment.

Tank Battery:

One (1) 400 bbl tank is present.

Tank battery is bermed with Vegetation (weeds) throughout.

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)		
Drums, Buckets, Containers	Other	Inadequate			
Comment	Well head: Chemical containers not within secondary containment.				
Corrective Action	By October 26, 2016, properly store chemical and fluid containers. 907 A, Management of Non E&P Waste, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.				Date: 10/26/2016

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
<p>On September 2, 2016 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of ARCH OIL AND GAS (Arch) Urie # 2 Location ID: 312772. The INSP included Tank Battery, the well (API 05-081-05288), tank battery, and Location. Weather was sunny to partially cloudy and temperature app mid 60s degree F and wind from the south. The well was not producing at time of inspection. For the most recent Field and Environmental Field inspection report of this facility, please refer to document # 673403544. At the time of the inspection, corrective actions (CAs) provided in that inspection had not been addressed. The overall inspection status shall remain the same as that document until all CAs have been completed. The following is a summary:</p> <p>Well head: Chemical containers not within secondary containment.</p> <p>Tank Battery: One (1) 400 bbl tank is present. Tank battery is bermed with Vegetation (weeds) throughout.</p> <p>Corrective Actions (CAs): Address the CAs outlined in the previous Inspection Report, Document 673403544. By October 26, 2016, properly store chemical and fluid containers. 907 A, Management of Non E&P Waste, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.</p>	fischera	09/27/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677900186	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965232
677900187	20160902 Arch Inspection Urie 2 Location ID 312772 .pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965227
677900188	INSP Summary 20160902 Arch Inspection J#2 Facility ID 312772 Photo log.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965228