



photo 1: Facing south along access road near the location. There are no BMP's to de-energize stormwater that flows down the side of the access road.



photo 2: Facing along the access road near the location. There is a sediment trap that has been installed.



photo 3: Facing southwest toward the location.



photo 4: Facing west along the north side of the location.



photo 5: Facing southeast toward the location.



photo 6: A ditch has been installed along the south cut slope side of the location. Additional BMP's should be installed to de-energize stormwater flow within the ditch.



photo 7: Facing northwest along the south side of the location. Additional BMP's should be installed to de-energize stormwater flow within the ditch.



photo 8: Facing west along the south side of the location.



photo 9: Facing north toward the location.



photo 10: Facing north at the east side of the location.