

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2016

Submitted Date:

09/30/2016

Document Number:

675203349

**FIELD INSPECTION FORM**

Loc ID 312484 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES, INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ellsworth, Stuart		Stuart.ellsworth@state.co.us	<a href="#">Engineering Supervisor</a>
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	<a href="#">All Inspections</a>
Tahmahkera, Kerry	(970) 563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>

**General Comment:**

[On site to check progress of repairs and timeline for MIT. Kelly hose broke at time of inspection. Operations stopped for day.](#)

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203349	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3965570</a>