

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

674103701**FIELD INSPECTION FORM**
 Loc ID 319801 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 18795Name of Operator: COLTON LIMITED LIABILITY COAddress: 475 17TH STREET #1200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Metzger, Tom		tmetzger@bsegllc.com	Out of Business

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201415	WELL	TA	07/30/2012	GW	001-06818	BERGMAN 1	TA

General Comment:

Location**Lease Road:**

Type	Access		
comment:	No decernable lease road. See photo. Weeds have taken over lease road.		
Corrective Action	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/14/2016

Overall Good: ☐**Emergency Contact Number:**

Comment:	No emergency contact # on sign, see photo.		
Corrective Action:	Install sign to comply with Rule 210	Date:	11/04/2016

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing on location, see photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/14/2016

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 201415 Type: WELL API Number: 001-06818 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA, well has been historically on a one year MIT plan, Last MIT was two years ago. No documents indicate well is no longer on one year MIT schedule.Corrective Action: Conduct an MIT. Date: 11/04/2016**BradenHead**Comment: Braden ehad is exposed at surface.

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment: [Battery has been removed.](#)

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Unable to locate former location of meter run house to see if risers from gathering line still exist.	rickardj	10/03/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103701	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3966974
674103702	Weeds at location and covering lease road.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3966961
674103703	Wellhead sign, missing emergency #.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3966962