

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

666802629**FIELD INSPECTION FORM**
 Loc ID 335497 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294537	WELL	PR	08/14/2008	GW	045-15514	SPECIALTY 34B-21-692	PR
294538	WELL	PR	08/09/2008	GW	045-15513	SPECIALTY 44B-21-692	PR
294664	WELL	PR	08/15/2008	GW	045-15563	SPECIALTY 33B-21-692	PR
294665	WELL	PR	08/14/2008	GW	045-15564	SPECIALTY 33D-21-692	PR
294666	WELL	PR	08/12/2008	GW	045-15565	SPECIALTY 34D-21-692	PR
294667	WELL	PR	08/16/2008	GW	045-15566	SPECIALTY 43B-21-692	PR
294668	WELL	PR	08/09/2008	GW	045-15567	SPECIALTY 43D-21-692	PR
294669	WELL	PR	08/14/2008	GW	045-15568	SPECIALTY 44D-21-692	PR

General Comment:[Facilities on location ID 335157](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

8

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Venting:

Yes/No YES

Comment: [Bradenhead valves open](#)

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	294537	Type:	WELL	API Number:	045-15514	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294538	Type:	WELL	API Number:	045-15513	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294664	Type:	WELL	API Number:	045-15563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294665	Type:	WELL	API Number:	045-15564	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294666	Type:	WELL	API Number:	045-15565	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294667	Type:	WELL	API Number:	045-15566	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294668	Type:	WELL	API Number:	045-15567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	294669	Type:	WELL	API Number:	045-15568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
		Check Dams	Pass			
		Sediment Traps	Pass			
Gravel	Pass					
		Culverts	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT