

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2016

Submitted Date:

10/05/2016

Document Number:

673803754**FIELD INSPECTION FORM**
 Loc ID 326773 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	
Prince, Nancy		nancy.prince@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245850	WELL	PR	06/15/2008	OW	123-13645	PIERCE 1-27	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	WIRE		
Corrective Action:		Date:	
Type	OTHER		
Comment:	FABRICATED METAL ON ELECTRICAL TRANSFORMER BOX		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	

Equipment:

Type: Deadman # & Marked	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:		Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	LEAK IN DOG HOUSE OF SEPARATOR/PAINT	Date:	
Corrective Action:	"Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d." REMOVE OR REMEDIATE STAINED SOIL	Date:	11/07/2016
Type: Ancillary equipment	# 1		
Comment:	ELECTRICAL TRANSFORMER	Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		40.634850,-104.766040
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	PRODUCED WATER LOAD OUT IS ON THE OUTSIDE OF CONTAINMENT BERM				
Corrective Action:	Date:				
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.634850,-104.766040
Comment:	Paint color does not comply with COGCC Rules				
Corrective Action:	"Repair and paint tanks per Rule 804." Date: 03/10/2017				

Paint

Condition	Inadequate
Other (Content)	

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	245850	Type:	WELL	API Number:	123-13645	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		PLUMBED TO SURFACE							
Corrective Action:								Date:	

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
DURING MY INSPECTION I OBSERVED AND PHOTGRAPHED WHAT APPEARED TO BE 2 CHUKAR PARTRIDGE ON LOCATION I CONTACTED BRANDON MARETTE CPW LGD IN REFERENCE TO THE CHUKAR PARTRIDGE ON LOCATION SEE ATTACHED PHOTOS	gomezj	10/05/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673803754	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969740
673803756	APPEARS TO BE CHUCKER PARTRIDGE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969719
673803757	CRUDE OIL TANKS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969720
673803758	SEPARATOR LEAK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969721