



Photo 1. View from the end of the access near the well pad entrance facing westward. Access road has not been reclaimed and needs to be fully reclaimed.



Photo 2. View of an area that is approximately 50 feet wide and 75 feet long where the access entered the well pad that has not revegetated and supports only a dense population of Russian thistle (*Salsola tragus*). This area needs to be re-seeded and likely mulched.



Photo 3. View of well pad from the southeastern corner facing center. Revegetation is progressing. Well pad contours do not match surrounding contours. Vegetation on the well pad is largely comprised of grasses such as needle and thread grass (*Hesperostipa comata*), western wheatgrass (*Pascopyrum smithii*), and cheatgrass (*Bromus tectorum*) along with subshrubs such as snakeweed (*Gutierrezia sarothrae*) and winterfat (*Krascheninekovia lanata*).



Photo 4. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 5. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 6. View of the beginning of Vegetation Transect 1, within the project disturbance, facing southward.




Photo 7. View of the beginning of Vegetation Transect 2, outside of the project disturbance, facing southward.