

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/05/2016

Submitted Date:

10/10/2016

Document Number:

674602875**FIELD INSPECTION FORM**
 Loc ID 318249 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |
| Canfield, Chris    |       | chris.canfield@state.co.us    |         |
| , KPK              |       | cogcc@kpk.com                 |         |
| Helgeland, Gary    |       | gary.helgeland@state.co.us    |         |
| Hazard, Ellice     |       | ellice.hazard@state.co.us     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 240962      | WELL | PR     | 03/20/1995  | OW         | 123-08750 | UPRR 43 PAN AM G 7 | EG          |

**General Comment:**

COGCC Follow-up engineering integrity inspection conducted on 10/05/2016 (previous EG field inspection doc #674602837 conducted on 09/27/2016). Details outlined in equipment/ flowline section of this report. Links to photos uploaded are available at the end of report.

**Inspected Facilities**Facility ID: 240962 Type: WELL API Number: 123-08750 Status: PR Insp. Status: EG**Flowline**

| #1 | Type: | of Lines |  |
|----|-------|----------|--|
|----|-------|----------|--|

Flowline Description

Flowline Type:                      Size: 3"                      Material: Fiberglass  
 Variance: No                      Age:                      Contents: Crude Oil

Integrity Summary

Failures:                      Spills:                      Repairs Made: Yes  
 Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed: No                      Test Result: Pass                      Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: The fiberglass flowline between the well site(s) and remote production battery has been repaired (at approximately 40.01160, 104.54890); A 12'-15' section of the fiberglass flowline has been cut out and replaced using HDPE pipe, couplers and clamps. Flowline pressure testing conducted (Labeled as UPRR 43 PAN AM G2 dated 9/28/16 Not Witnessed); Chart has been uploaded. As indicated on the prior field inspection, this flowline may service multiple UPRR 43 G wells in the area. The excavation has been backfilled and site regraded.

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <u>Note: The Actions Required on field inspection doc #681901446 conducted on 9/22/2016 must be completed as outlined (Housekeeping/ Weeds).</u> | maclarej | 10/10/2016 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                           | URL   |
|--------------|---------------------------------------|---|
| 674602875    | INSPECTION APPROVED                   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972165">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972165</a> |
| 674602882    | Excavation backfilled                 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972161</a> |
| 674602883    | Remediation completed/<br>site graded | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972162</a> |
| 674602884    | Flowline pressure test<br>chart       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972163">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972163</a> |