

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2016

Submitted Date:

10/10/2016

Document Number:

674602874**FIELD INSPECTION FORM**Loc ID 333225 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
KPK		cogcc@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239679	WELL	PR	12/02/1997	OW	123-07467	CAMENISCH 1	EG

**General Comment:**

The ACTIONS REQUIRED outlined on the previous field inspection doc#674602754 performed on 08/25/2016 have not been completed.

**Inspected Facilities**

Facility ID: 239679 Type: WELL API Number: 123-07467 Status: PR Insp. Status: EG

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: **CORRECTIVE ACTIONS REQUIRED HAVE NOT BEEN COMPLETED**

Corrective Action: **Contact COGCC EPS staff as required regarding anticipated completion of remediation work/ excavation closure; Provide COGCC Integrity group with a written (Email) description of well status, anticipated flowline repair/ replacement schedule, root cause of failures and repairs/ replacements completed or scheduled to be completed. Pressure test well site flowline prior to producing; Forward pressure testing data/ field chart to COGCC Integrity staff. Note: Ensure the integrity of the adjacent flowline exposed in the excavation (PDC Shirley #1 API 123-10525) is not compromised.**

Date: 09/29/2016

**COGCC Comments**

Comment	User	Date
Per COGCC Integrity Inspection doc #674602754 performed (flowline only) at this well site on August 25th, 2016: An open excavation was observed approximately 150' southeast of the pump jack/ wellhead. A form 27 doc #2313348 was received (Submitted by previous operator/ Foundation Energy) by the COGCC on 12/10/2014 that states the following: Upon discovery of flowline coupler leak, well was shut in and material was excavated down to the leak and stockpiled on plastic; leaking coupler was replaced. A change of operator (form 10 doc #400893404) was approved by the COGCC on 10/7/2015 (Buying Operator/ K P KAUFFMAN COMPANY INC). The spill remediation and flowline repair work appears to be in progress. The equipment/ flowline section of this report outlines the Actions Required identified during this field inspection. Photos uploaded can be accessed via links at end of report. Note: Last production reported February 2016.	maclarej	10/10/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602895	Well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972518">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972518</a>
674602897	Excavation/ Exposed flowlines	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972519">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972519</a>
674602898	Existing repairs to flowline	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972520</a>