

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2016

Submitted Date:

10/10/2016

Document Number:

674602874

FIELD INSPECTION FORM

Loc ID 333225 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| KPK | | cogcc@kpk.com | |
| Canfield, Chris | | chris.canfield@state.co.us | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Hazard, Ellice | | ellice.hazard@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 239679 | WELL | PR | 12/02/1997 | OW | 123-07467 | CAMENISCH 1 | EG |

General Comment:

The [ACTIONS REQUIRED](#) outlined on the previous field inspection doc#674602754 performed on 08/25/2016 have not been completed.

Inspected Facilities

Facility ID: 239679 Type: WELL API Number: 123-07467 Status: PR Insp. Status: EG

Flowline

| | | | |
|----|-------|----------|--|
| #1 | Type: | of Lines | |
|----|-------|----------|--|

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: **CORRECTIVE ACTIONS REQUIRED HAVE NOT BEEN COMPLETED**

Corrective Action: **Contact COGCC EPS staff as required regarding anticipated completion of remediation work/ excavation closure; Provide COGCC Integrity group with a written (Email) description of well status, anticipated flowline repair/ replacement schedule, root cause of failures and repairs/ replacements completed or scheduled to be completed. Pressure test well site flowline prior to producing; Forward pressure testing data/ field chart to COGCC Integrity staff. Note: Ensure the integrity of the adjacent flowline exposed in the excavation (PDC Shirley #1 API 123-10525) is not compromised.**

Date: 09/29/2016

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Per COGCC Integrity Inspection doc #674602754 performed (flowline only) at this well site on August 25th, 2016: An open excavation was observed approximately 150' southeast of the pump jack/ wellhead. A form 27 doc #2313348 was recieved (Submitted by previous operator/ Foundation Energy) by the COGCC on 12/10/2014 that states the following: Upon discovery of flowline coupler leak, well was shut in and material was excavated down to the leak and stockpiled on plastic; leaking coupler was replaced. A change of operator (form 10 doc #400893404) was approved by the COGCC on 10/7/2015 (Buying Operator/ K P KAUFFMAN COMPANY INC). The spill remediation and flowline repair work appears to be in progress. The equipment/ flowline section of this report outlines the Actions Required identified during this field inspection. Photos uploaded can be accessed via links at end of report. Note: Last production reported February 2016. | maclarej | 10/10/2016 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 674602874 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972524 |
| 674602895 | Well sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972518 |
| 674602897 | Excavation/ Exposed flowlines | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972519 |
| 674602898 | Existing repairs to flowline | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3972520 |