



photo 1: Facing south along the main access road to the location. The road has been graded.



photo 2: The culverts have been cleaned and maintained.



photo 3: It was noticed that some culverts do not have outlet protection which is a potential for erosion.



photo 4: The side of the access road was reggraded and seeded. Stormwater is now properly diverted.



photo 5: The main road switches back to the northeast at this point. Erosion issues have been corrected.



photo 6: Facing northeast along the main access road. Erosion issues have been corrected.



photo 7: Facing northwest toward the access road to the location. Erosion issues have been corrected.



photo 8: Facing north at the location.