

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/12/2016

Submitted Date:

10/14/2016

Document Number:

673403735

FIELD INSPECTION FORM

Loc ID 312968 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10407
Name of Operator: ANTLER ENERGY LLC
Address: PO BOX 104
City: BAGGS State: WY Zip: 82321

Findings:

- 9 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223072	WELL	PR	08/26/1981	GW	081-06434	POWDER WASH FEDERAL 28-3	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/27/2015
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	307-380-7616		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Dried annual weeds adjacent to heated tanks.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/24/2016

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:	1 of 4 tanks missing wildlife protection on exhaust.		
Corrective Action:	Install wildlife screen per Rule 605.b.(7).	Date:	11/14/2016
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CRUDE OIL	4	400 BBLs	HEATED STEEL AST		40.889610,-108.298660	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Inadequate		
Comment: Dried weeds growing immediately adjacent to heated tanks.						
Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details. Repair or install berms or other secondary containment devices per Rule 605.a.(4).					Date:	10/24/2016
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 223072 Type: WELL API Number: 081-06434 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.889770 Long: -108.299390

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: Metal Grid Netting Condition: Holes

Comment: _____

Corrective Action _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Two pit ids with this location 100421, 100424 neither associated with Antler as operator.

Corrective Action Please work with COGCC environmental staff Kris Nidel kris.nidel@state.co.us 970-871-1963 to identify which pit ID is appropriate, proper pit operation, and to close pit if not in use. Date: 11/24/2016

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.889570 Long: -108.298610

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: Mesh Netting Condition: Sagging into pit contents

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	Pit next to tanks. Two pit ids with this location 100421, 100424 neither associated with Antler as operator.	
Corrective Action	Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify which pit ID is appropriate, proper pit operation, and to close pit if not in use.	
		Date: <u>11/24/2016</u>

COGCC Comments

Comment	User	Date
Follow up to inspection from 4/12/2016 document number 673403113. All corrective actions remain outstanding. Landfarm fenced at 40.88988, -108.29894.	waldrone	10/12/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673403735	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3976979
673403745	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3976972