

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2016

Submitted Date:

10/18/2016

Document Number:

685501025**FIELD INSPECTION FORM**
 Loc ID 320211 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 3990Name of Operator: ARGONEX COMPANY LLCAddress: 8578 A GOLDEN PEAK DRIVECity: HIGHLANDS State: CO Zip: 80130**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Behrens, Vic	(303) 810-6382	behrens@netecin.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203066	WELL	PR	04/30/2006	OW	001-08472	CHAMPLIN (HER) 1-1	PR

**General Comment:**

Location				
<b>Lease Road:</b>				
Type	Main			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	CAN'T READ BATTERY SIGN NEED NEW SIGN			
Corrective Action:	Signs and Markers			Date: 11/18/2016
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	NEED NEW SIGN CAN'T READ IT			
Corrective Action:	Signs and Markers			Date: 11/18/2016
Emergency Contact Number:				
Comment:	NO EMERGENCY CONTACT NUMBER			
Corrective Action:	Signs and Markers			Date: 11/18/2016
<b>Good Housekeeping:</b>				
Type	TRASH			
Comment:	TRASH INSIDE TREATER HOUSE, PUMP HOUSE TRASH 5 GALLON BUCKETS, THIEF HATCHES INSIDE BERMS			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "			Date:
Type	UNUSED EQUIPMENT			
Comment:	REMOVE 300 BBL TANK UNUSED EQUIPMENT			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "			Date: 11/18/2016
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	Treater	<= 1 bbl		
Comment:	soiled dirt inside treater house			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "			Date: 11/18/2016
Crude Oil	Pump Jack	<= 1 bbl		
Comment:	soiled dirt inside pump jack house between motor mounts need cleaned out			

Corrective Action: "Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	Date: 11/18/2016
--	------------------

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>		corrective date
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment: need capacity signage					
Corrective Action: "Install sign to comply with Rule 210.b."					Date: 11/18/2016

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: berms in dis-repair				
Corrective Action: "Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."				Date: 11/18/2016

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.998830,-104.342180
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms in dis-repair will not hold capacity of oil prod tank			
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date: 11/18/2016

**Venting:**

Yes/No	NO	
Comment:	NO AIRS NUMBER	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: 203066	Type: WELL	API Number: 001-08472	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
	montoyaj	10/18/2016

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501025	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979534</a>
685501028	well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979511">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979511</a>
685501029	soiled dirt	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979512</a>
685501030	trash and soiled dirt	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979513">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979513</a>
685501031	oil spill	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979514">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979514</a>
685501032	trash and recycle pump	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979515">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979515</a>
685501033	trash	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979516</a>
685501034	battery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979517">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979517</a>
685501036	unused tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979518">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979518</a>
685501037	unused equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979519">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979519</a>
685501038	soiled dirt concrete vault	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979520</a>
685501039	soiled dirt	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979521</a>
685501040	fill in holes around pit screen	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979522">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979522</a>
685501041	repair fence pit screen	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979523">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979523</a>
685501042	low spot on pit screen	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979524</a>
685501043	berms need rebuilt	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979525">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979525</a>