



**photo 1:** Facing northeast toward the location from the access road.



**photo 2:** Facing east toward the location.



**photo 3:** There are piles of debris that remain on location and reclamation has not been performed.



**photo 4:** There is undesirable weed growth (Russian thistle) throughout the location.



**photo 5:** Facing southwest toward the location.



**photo 6:** Facing north toward the surrounding reference area.