

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/19/2016
Submitted Date:
10/20/2016
Document Number:
675203478

FIELD INSPECTION FORM

Loc ID 312588 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Giboo, David	(970) 319-2211	dgiboo@blm.com	Lead Petroleum Engineering Tech
Gross, Jason		jrgross@fs.fed.us	
Encana,		cogcc.inspections@encana.com	All Inspections
Ellsworth, Stuart		Stuart.ellsworth@state.co.us	Enginerring Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221972	WELL	SI	01/01/1999	GW	077-08574	DIVIDE CREEK UNIT 22	PA

General Comment:

[Well has been plugged, equipment removed from location and final reclamation has taken place. Form 6 \(s\) Doc#1884390 still in review.](#)

Inspected Facilities

Facility ID: 221972 Type: WELL API Number: 077-08574 Status: SI Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203479	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3981176