

Construction Inspection



Photo 1. Photo taken from northern location, facing West. Ditch and berm constructed along northern location to control run-on onto location.

Construction Inspection



Photo 2. Photo taken from northern, facing South, towards topsoil pile.

Construction Inspection



Photo 3. Photo taken from western topsoil pile, facing South. Ditch and berm constructed around outer perimeter of topsoil pile to control run-off.

Construction Inspection



Photo 4. Photo taken from southern location, facing East. Ditch and berm constructed along southern location to control run-off. Contractor mentioned that additional BMPs would be installed along the southern location.

Construction Inspection



Photo 5. Photo taken from eastern location, facing South. Ditch and berm constructed along eastern location to control run-off.