



Photo 1. View of wood debris in the southwestern portion of the project area.





Photo 2. View of unknown soil management area in the northern portion of the project area. Area is bermed and soil is in rows.





Photo 3. View of the project area from the northeastern corner facing center.



Photo 4. View of the eastern portion of the project area form the northeastern corner facing center.





Photo 5. View of straw wattles on the northern edge of the project area.





Photo 6. View of access road that is still in place from well pad entrance facing southward.