

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2016

Submitted Date:

10/21/2016

Document Number:

679400099**FIELD INSPECTION FORM**
 Loc ID 319853 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Montoya, John		john.montoya@state.co.us	
Donato, Scot	303-398-0537 direct	sdonato@gwogco.com	Regulatory Mgr DJ
Axelson, John		john.axelson@state.co.us	
Precup, Jim		james.precup@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201588	WELL	PR	12/12/2006	GW	001-06991	CHAMPLIN 67 AMOCO C 1	PR

**General Comment:**

Environmental inspect regarding status of remediation #9465. Pit and vault removed and excavation has been backfilled. Work appears the be recent. No issues with TB. See photos. Pit status will remain AC until remediation is closed.

Inspected Facilities									
Facility ID:	201588	Type:	WELL	API Number:	001-06991	Status:	PR	Insp. Status:	PR

--

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Environmental inspect regarding status of remediation #9465. Pit and vault removed and excavation has been backfilled. Work appears the be recent. No issues with TB. See photos. Pit status will remain AC until remediation is closed.	chessonr	10/21/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679400101	Tank Batttery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982714</a>
679400102	Meter shed and treater	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982715</a>
679400103	Wellhead and pump jack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982716</a>
679400104	Pit excavation area - looking south toward crude tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982717</a>
679400105	Pit excavation area - looking south	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982718</a>
679400106	treater	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982719</a>