

Construction Inspection

10/21/2016

Operator: Grand Mesa Operating Co

Location ID: 442964

Washington County, CO

SESW Section 24 T5S R54W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



10.21.2016 14:18

Figure 1: Photo taken from Washington County Road 2, facing north. Photo shows approximate area where access road will be constructed.



Figure 2: Photo taken from south end of the location, facing east. Photo shows construction in process.



Figure 3: Photo taken from south end of the location, facing northeast. Photo shows construction in process.



Figure 4: Photo taken from south end of the location, facing north. Photo shows construction in process.



Figure 5: Photo taken from south end of the location, facing northwest. Photo shows construction in process.



10.21.2016 14:22

Figure 6: Photo taken from south end of the location, facing west. Photo shows construction in process.



Figure 7: Photo taken from the west end of the location, facing north. Photo shows surface roughening has been constructed in conjunction with berms as a stormwater and sediment control BMP



Figure 8: Photo taken from the west end of the location, facing north. Photo shows berms along the western and northern perimeter of the location have been adequately tracked.



Figure 9: Photo taken from the northwest corner of the location, facing south. Photo shows surface roughening used in conjunction with berms as a stormwater and sediment control BMP.



Figure 10: Photo taken from the northwest corner of the location, facing east. Photo shows surface roughening used in conjunction with berms as a stormwater and sediment control BMP.



Figure 11: Photo taken from the northeast corner of the location, facing west. Photo shows surface roughening implemented around perimeter of location. Topsoil stockpile to the top right of the photo.



Figure 12: Photo taken from the northeast corner of the location, facing south. Photo shows surface roughening implemented around perimeter of location.



Figure 13: Photo taken from the southeast corner of the location, facing west. Photo shows surface roughening implemented around perimeter of location.



Figure 14: Photo taken from the southeast corner of the location, facing north. Photo shows surface roughening implemented around perimeter of location



Figure 15: Photo taken from the south end of the location, facing south. Photo shows surface roughening implemented around perimeter of location