

## Final Reclamation Inspection



**Photo 1.** Photo taken from center of location, facing West. Native, perennial grass has established on the western half of the location but lacks on the eastern half of the location. Native, perennial shrubs have not established at location which is not reflective of reference areas.


## Final Reclamation Inspection



**Photo 2.** Photo taken from center of location, facing North. Native, perennial grass has established on the western half of the location but lacks on the eastern half of the location. Native, perennial shrubs have not established at location which is not reflective of reference areas.



# Final Reclamation Inspection



**Photo 3.** Photo taken from center of location, facing East. Native, perennial grass has established on the western half of the location but lacks on the eastern half of the location. Native, perennial shrubs have not established at location which is not reflective of reference areas.



## Final Reclamation Inspection



**Photo 4.** Photo taken from center of location, facing South. Native, perennial grass has established on the western half of the location but lacks on the eastern half of the location. Native, perennial shrubs have not established at location which is not reflective of reference areas.



# Final Reclamation Inspection



**Photo 5.** Reference photo taken west of location, facing South. Location is still IN-PROCESS. Location is not reflective of reference areas as illustrated with this photo.