



Photo 1. View of the western portion of the project from the northwestern corner facing southward. It appears western portion was seeded since last inspection.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of northern cut-slope with sparse revegetation.



Photo 4. View of cobble run-down placed to stabilize erosional channel in the northeastern portion of the project area.



Photo 5. View of small pieces of debris in the southern portion of the interim reclamation area.