

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/21/2016
Submitted Date:
10/26/2016
Document Number:
685301629

FIELD INSPECTION FORM

Loc ID 334030 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10254
Name of Operator: RED MESA HOLDINGS/O&G LLC
Address: 5619 DTC PARKWAY - STE 800
City: GREENWOOD State: CO Zip: 80111

Findings:

- 19 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
T., Alfred	856-767-3000	atgiuliano@giulianomiller.com	All Red Mesa Holdings Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290197	WELL	PR	08/17/2007	OW	067-09356	DYEHARD 3A	SI

General Comment:

[Inspection conducted to verify current wellhead integrity and location condition. See link at end of report for path to downloadable pictures.](#)

Location			
Lease Road:			
Type	Access		
comment:	Requires maintenance. Covered in weeds.		
Corrective Action:	Maintain and repair lease road to comply with Rule 604.c.(2).S.	Date:	11/28/2016
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	COGCC contact information sticker placed on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	COGCC contact information sticker placed on wellhead sign.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	COGCC contact information sticker placed on tank and wellhead sign.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	Location perimeter, patches on location, and access road covered in weeds.		
Corrective Action:	Remove weeds to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	11/11/2016
Type	DEBRIS		
Comment:	Production related trash and debris scattered around location.		
Corrective Action:	Clean up trash and debris to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	11/08/2016
Type	UNUSED EQUIPMENT		
Comment:	Unused concrete slab on E side of wellhead.		
Corrective Action:	Remove concrete slab to comply with Rule 603.f using the Rule 603.f guidance document.	Date:	11/28/2016
Type	UNUSED EQUIPMENT		
Comment:	Pump Jack drive belt cover removed and left on location.		
Corrective Action:	Install or remove cover to comply with Rule 603.f using the Rule 603.f guidance document.	Date:	11/28/2016
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Ancillary equipment	# 1	corrective date
Comment:	Electric Service.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Knock out cylinder at back of meter run.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Corrective action not completed.		
Corrective Action:	Mark all deadmen to comply with Rule 1003.f.	Date:	04/13/2015
Type: Pump Jack	# 1		
Comment:	Drive belf cover removed and lying on the ground.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are weathering.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 290197 Type: WELL API Number: 067-09356 Status: PR Insp. Status: SI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Fail	

Comment: Action Required not completed; Unlabeled container with fluid contents near pump jack. The plastic container is cracked and deteriorating. There is no spill prevention in place.

Corrective Action: Remove container from location, or properly store and label to comply with Rule 1002.f.

Date: 04/13/2015

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301646	Weeds on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985099
685301647	Cracker container of fluid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985100
685301648	Belt drive cover	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985101
685301649	Access road covered in weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985102
685301650	Concrete slab	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985103