

Final Reclamation Inspection- Overview



Aerial imagery taken 2011 using COGCC GISOnline database. Tank battery location still has pipeline risers. Need to remove risers per Rule 1004.

Final Reclamation Inspection



Photo 1. Photo taken from center of well location, facing West. No evidence of disturbance. Uniform vegetative crop growth and density throughout location.

Final Reclamation Inspection



Photo 2. Photo taken from center of well location, facing North. No evidence of disturbance. Uniform vegetative crop growth and density throughout location.

Final Reclamation Inspection



Photo 3. Photo taken from center of well location, facing East. No evidence of disturbance. Uniform vegetative crop growth and density throughout location.

Final Reclamation Inspection



Photo 4. Photo taken from center of well location, facing South. No evidence of disturbance. Uniform vegetative crop growth and density throughout location.

Final Reclamation Inspection



Photo 5. Reference photo taken west of location, facing West. Location appears to be reflective of crop reference areas.

Final Reclamation Inspection



Photo 6. Photo taken from tank battery location, facing East. Need to remove pipeline risers per Rule 1004.

Final Reclamation Inspection



Photo 7. Photo taken from tank battery location, facing North. Need to remove pipeline risers per Rule 1004.