

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. Vegetative growth IN-PROCESS at location. Evidence of seeding attempt evident from seed drilling rows but areas throughout location still have bare patches with little to no vegetative growth that is not reflective of reference areas.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. Vegetative growth IN-PROCESS at location. Evidence of seeding attempt evident from seed drilling rows but areas throughout location still have bare patches with little to no vegetative growth that is not reflective of reference areas.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. Vegetative growth IN-PROCESS at location. Evidence of seeding attempt evident from seed drilling rows but areas throughout location still have bare patches with little to no vegetative growth that is not reflective of reference areas.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. Vegetative growth IN-PROCESS at location. Evidence of seeding attempt evident from seed drilling rows but areas throughout location still have bare patches with little to no vegetative growth that is not reflective of reference areas.

Final Reclamation Inspection



Photo 5. Photo taken from the western location, facing East. Vegetative growth IN-PROCESS at location. Evidence of seeding attempt evident from seed drilling rows but areas throughout location still have bare patches with little to no vegetative growth that is not reflective of reference areas.

Final Reclamation Inspection



Photo 6. Reference photo taken west of location, facing West. Location still IN-PROCESS as vegetative growth is not reflective of reference areas.