

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/18/2016
Submitted Date:
10/18/2016
Document Number:
674703239

FIELD INSPECTION FORM

Loc ID 335240 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211008	WELL	TA	05/09/2012	GW	045-06766	UNOCAL MV 18-32	PR
274575	WELL	PR	07/27/2005	GW	045-13362	WILLIAMS PRODUCT RMT GM 333-32	PR
274588	WELL	PR	06/20/2005	GW	045-13363	WILLIAMS PRODUCTION RMT GM 433-32	PR
274669	WELL	PR	07/01/2005	GW	045-13369	WILLIAMS PRODUCTION RMT GM 33-32	PR

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Road is on a steep grade most likely require more frequent maintenance.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment has been removed rom location.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	1 panel and the gate are leaning in towards the wells.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical container at wells		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	YES		

Comment:	Bradens are open to vent.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>211008</u>	Type: <u>WELL</u>	API Number: <u>045-06766</u>	Status: <u>TA</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Well was Shut in on previous inspection and no Form 21 found in COGCC database. Operator made available copy of Form 21 submitted to BLM. Form 21 doc # 401072455. Well has been reworked and returned to production.		
Corrective Action:		Date:	
Facility ID: <u>274575</u>	Type: <u>WELL</u>	API Number: <u>045-13362</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>274588</u>	Type: <u>WELL</u>	API Number: <u>045-13363</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>274669</u>	Type: <u>WELL</u>	API Number: <u>045-13369</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			Additional gravel added to road
		Compaction	Pass			
Ditches	Pass					New cut ditch around cut wall.
		Ditches	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Document #401072455 Form 21 provided by operator and well now back in production. Additional BMPs added and maintenance existing BMPs. Unused/unneeded equipment has been removed from location and down hill slope.	longworm	10/18/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703239	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3980944