

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2016

Submitted Date:

10/20/2016

Document Number:

675203473**FIELD INSPECTION FORM**
 Loc ID 322380 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|---------------------------------|---------------------------------|
| Allred, Josh | (970) 629-5914 | jallred@foundationenergy.com | Field Supervisor |
| Contact, General | | regulatory@foundationenergy.com | Regulatory |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | NW Supervisor |
| Giboo, David | (970) 319-2211 | dgiboo@blm.com | Lead Petroleum Engineering Tech |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210388 | WELL | PR | 08/02/1978 | GW | 045-06144 | FEDERAL 29-16 | PR |

General Comment:

Follow up inspection to Doc#675203401, 675203386, 675203259, and 675203143. COGCC staff scheduled to meet with Foundation Energy Management LLC representative at 8:30am. Rep arrived over an hour after set time. Rep accompanied COGCC staff to location. Pit had been maintained to meet corrective actions from previous inspections. The corrective action for installing a berm/containment around the produced water tank had not been met.

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 210388 | Type: WELL | API Number: 045-06144 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: EvaporationLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: Comment: Corrective actions have been met from previous inspections.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 675203473 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3985712 |
| 675203474 | Repaired Pit | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3981127 |