

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

10/27/2016

Document Number:

685100087**FIELD INSPECTION FORM**
 Loc ID 312854 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 36200Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Richard		R.Miller@gryenberg.com	
Edelen, Randy		r.edelen@gryenberg.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100600	PIT	AC			-	CHIVINGTON 1	EI
222617	WELL	SI	05/07/2013	OW	081-05709	CHIVINGTON 1	EI

General Comment:

COGCC Environmental staff (Kris Neidel) inspected the location at the Chivington #1 on 10/25/2016. Weather was 62 deg and cloudy. Grynberg notified the COGCC on 10/24/2016 that the material that they imported for backfill may have been contaminated with trash. Upon arrival on location, Grynberg contractors has spread much of the fill material across the pad to assess the extent of forging material that may be in the fill soil. Staff witnessed crews picking up any forging material that was in the soil while backfilling the south side of the main pit excavation, near the area of former sample location "5". There was some forging material (trash, pvc) in the fill soil, no forging material was witnessed being placed in the pit. The amount of trash is estimated to be approximately one half of a trash bag. A soil sample was collected by the COGCC and will be analyzed and compared to table 910-1 values. There is a pile of soil, approximately 80yds, that was excavated from the remaining contamination in the pit that needs to be disposed of offsite (see photos for detail).

Inspected FacilitiesFacility ID: 100600 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 222617 Type: WELL API Number: 081-05709 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100088	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986290