

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/27/2016  
Submitted Date:  
10/27/2016  
Document Number:  
675203514

**FIELD INSPECTION FORM**

Loc ID 324168 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**  
2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone | Email                        | Comment                         |
|--------------|-------|------------------------------|---------------------------------|
| Encana,      |       | cogcc.inspections@encana.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 260769      | WELL | PR     | 11/06/2004  | GW         | 045-07910 | BENTLEY 11-43 | PR          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |                      |       |                      |
|--------------------|----------------------|-------|----------------------|
| Comment:           | <input type="text"/> |       |                      |
| Corrective Action: | <input type="text"/> | Date: | <input type="text"/> |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | Vegetation debris in tank containment. Noted on previous inspection.               |       |            |
| Corrective Action: | Comply with Rule 603.f using the Rule 603.f guidance document for further details. | Date: | 11/28/2016 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| METHANOL           | 1 | <50 BBLS | STEEL AST |          | ,      |
| Comment:           |   |          |           |          |        |
| Corrective Action: |   |          |           |          | Date:  |

Paint

|                  |          |  |  |
|------------------|----------|--|--|
| Condition        | Adequate |  |  |
| Other (Content)  |          |  |  |
| Other (Capacity) |          |  |  |
| Other (Type)     |          |  |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents   | # | Capacity | Type      | Tanak ID | SE GPS |
|------------|---|----------|-----------|----------|--------|
| CONDENSATE | 2 | 300 BBLS | STEEL AST |          | ,      |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 260769 Type: WELL API Number: 045-07910 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            | Gravel                  | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 675203518    | Tank containment | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986331</a> |